

CANADIAN METAL-AD CORPORATION
42 REGAN RD, UNIT 17
BRAMPTON, ONTARIO
L7A 1B4
1-800-899-6926
Email: info@metalad.ca



COPPER ACID HIGH SPEED - 2903

DANGER

EMERGENCY NUMBER: 416-276-9343

HAZARD STATEMENT

Hazard statement: H302 Harmful if swallowed.
H315 - Causes severe skin burns and eye damage.

PRECAUTION:

P260 - Do not breathe vapours/spray.
P264 Wash contaminated skin thoroughly.
P270 - Do not eat, drink or smoke when using this product. P280 - Wear protective gloves/protective clothing/eye protection/face protection.
P284 - [In case of inadequate ventilation] wear respiratory protection. P301 + P310 - IF SWALLOWED: Immediately call a POISON CENTER/doctor/...
P302 + P352 - IF ON SKIN: Wash with plenty of water/... P304 + P340 - IF INHALED: Remove person to fresh air and keep comfortable for breathing.
P305 + P351 + P338 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. P501 - Dispose of contents/container in accordance with national regulations.

Contains: COPPER FLUOROBORATE,
FLUOROBORIC ACID

VOLUME: 1 LTRS

CANADIAN METAL-AD CORPORATION
42 REGAN RD, UNIT 17
BRAMPTON, ONTARIO
L7A 1B4
1-800-899-6926
Email: info@metalad.ca



COPPER ACID HIGH SPEED - 2903

DANGER

EMERGENCY NUMBER: 416-276-9343

HAZARD STATEMENT

Hazard statement: H302 Harmful if swallowed.
H315 - Causes severe skin burns and eye damage.

PRECAUTION:

P260 - Do not breathe vapours/spray.
P264 Wash contaminated skin thoroughly.
P270 - Do not eat, drink or smoke when using this product. P280 - Wear protective gloves/protective clothing/eye protection/face protection.
P284 - [In case of inadequate ventilation] wear respiratory protection. P301 + P310 - IF SWALLOWED: Immediately call a POISON CENTER/doctor/...
P302 + P352 - IF ON SKIN: Wash with plenty of water/... P304 + P340 - IF INHALED: Remove person to fresh air and keep comfortable for breathing.
P305 + P351 + P338 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. P501 - Dispose of contents/container in accordance with national regulations.

Contains: COPPER FLUOROBORATE,
FLUOROBORIC ACID

VOLUME: 1 LTRS

CANADIAN METAL-AD CORPORATION
42 REGAN RD, UNIT 17
BRAMPTON, ONTARIO
L7A 1B4
1-800-899-6926
Email: info@metalad.ca



COPPER ACID HIGH SPEED - 2903

DANGER

EMERGENCY NUMBER: 416-276-9343

HAZARD STATEMENT

Hazard statement: H302 Harmful if swallowed.
H315 - Causes severe skin burns and eye damage.

PRECAUTION:

P260 - Do not breathe vapours/spray.
P264 Wash contaminated skin thoroughly.
P270 - Do not eat, drink or smoke when using this product. P280 - Wear protective gloves/protective clothing/eye protection/face protection.
P284 - [In case of inadequate ventilation] wear respiratory protection. P301 + P310 - IF SWALLOWED: Immediately call a POISON CENTER/doctor/...
P302 + P352 - IF ON SKIN: Wash with plenty of water/... P304 + P340 - IF INHALED: Remove person to fresh air and keep comfortable for breathing.
P305 + P351 + P338 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. P501 - Dispose of contents/container in accordance with national regulations.

Contains: COPPER FLUOROBORATE,
FLUOROBORIC ACID

VOLUME: 1 LTRS

CANADIAN METAL-AD CORPORATION
42 REGAN RD, UNIT 17
BRAMPTON, ONTARIO
L7A 1B4
1-800-899-6926
Email: info@metalad.ca



COPPER ACID HIGH SPEED - 2903

DANGER

EMERGENCY NUMBER: 416-276-9343

HAZARD STATEMENT

Hazard statement: H302 Harmful if swallowed.
H315 - Causes severe skin burns and eye damage.

PRECAUTION:

P260 - Do not breathe vapours/spray.
P264 Wash contaminated skin thoroughly.
P270 - Do not eat, drink or smoke when using this product. P280 - Wear protective gloves/protective clothing/eye protection/face protection.
P284 - [In case of inadequate ventilation] wear respiratory protection. P301 + P310 - IF SWALLOWED: Immediately call a POISON CENTER/doctor/...
P302 + P352 - IF ON SKIN: Wash with plenty of water/... P304 + P340 - IF INHALED: Remove person to fresh air and keep comfortable for breathing.
P305 + P351 + P338 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. P501 - Dispose of contents/container in accordance with national regulations.

Contains: COPPER FLUOROBORATE,
FLUOROBORIC ACID

VOLUME: 1 LTRS